



# Compass Swivel Overhead Installation Instructions

(Base Part #'s: 69400NS, 69400, 69410NS & 69410 - Single Color or Color Selection)

PARTS/TOOLS NEEDED:			
Compass Overhead Light	Mounting Screws (Qty: 3)	Butt Splice Connectors (Not Provided)	Power Drill & 2" Hole Saw

## IMPORTANT SAFETY INSTRUCTIONS. READ CAREFULLY FOR YOUR PROTECTION AND SAVE ALL INSTRUCTIONS.

- \*Disconnect power before installing, adding or changing any component.
- \*To avoid a hazard to children, account for all parts and destroy all packing materials.
- \*It is recommended that fuse protection be added to the positive(+) input.

**1.** Determine the installation location and use the light to mark holes. Drill holes for the screws and cut out 2" hole for light.

69400NS/69410NS




69400/69410




**2.** Wire the light using the wiring diagrams below. Test the light.

### Single Color Wire Diagram




### Color Selection Wire Diagram




**3. 69400NS/69410NS** | Screw down the light using the provided screws. **69400/69410** | Push clips on both sides of light up and slide housing and clips through hole. Clips will snap down and hold the light in place.

69400NS/69410NS



69400/69410



For warranty information please visit [www.itc-us.com/warranty](http://www.itc-us.com/warranty)

3030 Corporate Grove Dr • Hudsonville • MI • 49426

Phone: 616-396-1355 • Fax: 616-396-1152 • [www.itc-us.com](http://www.itc-us.com) • [sales@itc-us.com](mailto:sales@itc-us.com) • DOC#: 710-00112 • Revision A: 04/08/19